

PCB ID: WhatsApp_Image_2025-09-23_at_13

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue