

PCB ID: image_2025-09-27_232601869

Spur - Severity: 4 - Cause: Etching / unwanted copper

Spur - Severity: 4 - Cause: Etching / unwanted copper