REMAINING ALIGNMENT CHECK — section through the office frontage



Green line illustrates the clash if the road stays fixed; it is not an implemented grass placement. Road grade shown at the exit stair.