

SunProof AI

Sun Condition Verification Note

PROPERTY DETAILS

Address	Karl Johans gate 1, Oslo
Facade	N
Month	July
Analysed	6 May 2026

VERDICT: POSSIBLY MISLEADING

EXPLANATION

Photo shows sun, but calculations show a N-facing facade gets no sun in July. The warm golden-hour light visible in the image is geometrically inconsistent with this orientation.

SOLAR CALCULATION SUMMARY

N-facing facade receives no direct sun in July. Claims of sunlight would be misleading.

DISCLAIMER

This document is a compliance-support note, not legal advice. The verdict is generated by an AI model analysing a single photograph and deterministic solar geometry calculations. Results depend on the accuracy of the provided address, facade orientation, and image quality. SunProof AI does not guarantee correctness and accepts no liability.