



VEHICLE INSPECTION

Vin : WBS22DM0708F16258 Model: M2

Inspection date : 05-Mar-2025 08:22:25

Route : BMW Vehicle Distribution Centre to BMW Bryanston

Exterior Inspection Results

Exterior Comments : _

Exterior Mirrors : Present

Vehicle Colour : M ZANDVOORT BLUE

Interior Inspection Results

Fuel

Low but acceptable

Head Rests

Present

Interior

Clean

Cigg / Lighter /Ash
Tray

Not Supplied

Interior Mirrors

Present

Number of Keys

2

Owners manual

Present

Spare Wheel/Jack

Not Supplied

Sun Visors

Present

Wheel Covers/Hub
Caps

Present

Radio

Present

Wipers

Present

Radio Antenna

Present

Additional Interior Note

Checked by :

Client Representative

Client Signature

Makatu Representative

Nthabi

Makatu Rep Signature

A handwritten signature in black ink, appearing to be a stylized 'P' or similar character.

Record ID : 4417696000008870054

Interior

Added Time

Added User

Exterior

