Lender Asset Verification Inspection Report

ASSET TYPE

- [x] Car
- [ ] Bike
- [ ] Caravan
- [ ] Heavy Vehicle
- [ ] Boat
- [ ] Equipment
- [ ] Other

MAKE Mercedes-Benz	**MODEL** C-Class
BADGE C300	**YEAR** 2022
VIN WDD2050472F123456	**REGISTRATION PLATE** MB3NZ
REGISTRATION EXPIRY 28/02/2027	**ODOMETER** 51,890 km
BODY Sedan	**COLOUR** Black



INSPECTION SUMMARY

OVERALL CONDITION OF VEHICLE

- [x] GOOD
- [ ] FAIR
- [ ] POOR

ADDITIONAL INSPECTOR COMMENTS

Inspector comments not supplied.

SAMPLE

Lender Asset Verification Inspection Report

PHOTO VERIFICATION

Guided photo capture
Each photo in the report is captured using the Auto Verifi app. The user follows the guided walkaround to capture the images while onsite with the vehicle. A time and date stamped record of the vehicle, in addition to its GPS location, is also recorded by the Auto Verifi app.



Front
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km



Rear
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km



Left passenger side
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km



Right driver side
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km

AI DAMAGE SCAN

No significant damage detected

Front	Rear	Left passenger side	Right driver side
No damage detected	No damage detected	No damage detected	No damage detected

The walkaround photos are scanned by AI using the Auto Verifi app to detect visible exterior damage. If damage is detected, the result shows “Damage detected” and the affected areas (for example, front bumper or left rear door) are marked in red on the walkaround photos. The scan covers visible exterior damage only and is not a mechanical or structural assessment.

SAMPLE

IDENTIFICATION PHOTOS



VIN identification
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km



Odometer reading
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km



Registration papers
GPS location: Gladesville NSW 2111
Date and time: 24/10/2026 · 10:30 am EST
Odometer: 51,890 km

SAMPLE

Disclaimer

Purpose and Scope

This report has been prepared by Auto Verifi solely for the purpose of vehicle asset verification in connection with a lender's finance application, asset security assessment or ongoing asset verification requirements. It is not a comprehensive vehicle inspection, mechanical assessment, valuation or certification of ownership.

AI Scan Technology and Data Capture

Vehicle images, identification details, inspection date, time and geographic location are captured and/or processed using Auto Verifi's AI-enabled scanning technology. Information may be automatically extracted, interpreted and recorded using artificial intelligence, optical character recognition (OCR), device metadata and location services.

While reasonable measures are taken to support data accuracy, AI-generated or extracted information may contain errors, omissions or inaccuracies. Date, time and location records may depend on device settings, GPS availability, network connectivity and other technical factors. Such information does not independently establish that a vehicle or its identifiers are authentic.

Inspection Limitations

The inspection is limited to the information, images and vehicle attributes captured and recorded at the time of assessment. Unless expressly stated otherwise, Auto Verifi does not:

- Guarantee the authenticity, originality or integrity of the VIN, engine number, registration plates or other vehicle identifiers.
- Certify the vehicle's mechanical condition, roadworthiness, safety, structural integrity or fitness for purpose.
- Guarantee legal ownership, clear title, absence of encumbrances or freedom from fraud, theft or misrepresentation.
- Verify the accuracy of the odometer reading or the vehicle's complete history.
- Warrant that all damage, defects, alterations or discrepancies have been identified.

Reliance and Liability

This report provides supporting information for asset verification purposes only. Any finance approval, lending, valuation or security decision remains the sole responsibility of the lender.

Auto Verifi does not guarantee the accuracy or completeness of information obtained from third-party sources or generated through automated assessment processes. To the extent permitted by applicable law, Auto Verifi excludes liability for losses arising from reliance on inaccurate, incomplete or misleading information, except to the extent caused by its own negligence, breach of contract or other liability that cannot lawfully be excluded.

Legal and Regulatory Requirements

This report does not replace any identity verification, anti-money laundering, responsible lending, security registration, title verification or other due diligence obligations applicable to the lender under Australian law.

Nothing in this disclaimer excludes, restricts or modifies any rights, guarantees or remedies that cannot lawfully be excluded under the Australian Consumer Law or other applicable legislation.

Report Validity

The findings reflect the vehicle and information available at the recorded inspection date and time only. Auto Verifi does not warrant the vehicle's subsequent condition, location, possession or ownership.

© Auto Verifi. All rights reserved. Confidential – prepared for the commissioning client and its authorised representatives.

SAMPLE