

Daily Time Sheet

No.STN-1-270117071632

Plumber: Doe, Reinhardt

Site: House Steyn

Specific location:

Bathroom

Detailed Point:

Basin

Completion Status:

SecondFix

Description of work done

Removal of rust

Time spent:

Plumber 1 h 30 min

Assistant(s) 3 h 20 min

Part of Original Quote?

Yes

Quote No:

N/A

Additional Work: S.I. Number

N/A

Signiture (Site Manager)

Material used

BOM No.	Code	Description	Quantity	Supplier
	622.311.00.5	Mepla Red Tee 20x16x20mm	12,00	Builder's Hardware
	621.505.00.5	Mepla coupling dia 16mm	45,00	Timber City
		Escavate	10m	

Signed: _____

Name: Doe, Reinhardt

Date: 27-01-17