### JOHNSON LIFTS PRIVATE LIMITED

PLOT NO.R7/2 & 3, NORTH MAIN ROAD, ANNA NA GAR WESTERN EXTN. CHENNAI PIN: 600101



### SERVICE REPORT

# **BREAKDOWN SERVICE DETAILS**

JOB NO : L-A1431 Nature Of Contract : SSM

Customer Name : MANASAROVAR OWNERS Breakdown No : TN01221201624

ASSOCIATION Technician Name : THIRUGNANAM A

Location/Address : No. T-25, OLD No. T-11, Employment No : E3462

Date : Dec 20, 2022 Time reported : Dec 20, 2022, 12:38:54 PM

Time Left : Dec 23, 2022, 9:12:15 AM

### **NATURE OF WORK**

### **BREAKDOWN SERVICE**

Type of Breakdown : LIFT NOT WORKING
Breakdown Status : Completed in full

Areas of Breakdown : [OTHERS - MATERIAL RELATED]

### **FEEDBACK REMARKS**

### **REMARKS**

CUSTOMER SIDE ARD BATTERY VOLTAGE LOW SOME RELAY CHA NGE QUOTATION ISSUED LIFT NO TROUBLE INFORM TO CUSTOM

#### **SIGNATURE**

## **SIGNATURE**



Technician Signature

Date: 23/12/2022 09:12 am



**Customer Signature** 

Date: 23/12/2022 09:12 am

CAUTION: IF DOOR OPEN KEY IS USED, ENSURE THAT DOOR IS FULLY CLOSED.

 $Regd.\ Office: No.1, East\ Main\ Road,\ Anna\ Nagar\ West\ Extension,\ Chennai-600\ 101.$ 

WEBSITE: www.Johnsonliftsltd.com,PH:261520003/4/5/6

1 of 1 23-12-2022, 11:33