

NDT INSPECTION REPORT - SAMPLE

Aircraft: MSN-001

Component: Left Wing Upper Skin, Station 4500

Method: Ultrasonic C-Scan

Result: PASS - Void Fraction 0.8%