

BhuDrishti 3D — Vertical Property Validation Report

Report ID: RPT-31BA0439ACCD
Generated: 2024-11-20T12:00:00+05:30
Generated By: BhuDrishti3D_Pipeline_v0.9.1

1. Summary

Field	Value
Parent ULPIN	7A4B9C2D8E1F6G
Building Name	Shanti Heights Tower-A
Number of Floors	6
Total Units	8
Valid Units	5
Conflicts Detected	3
Overall Confidence	87.0%
■ Geometric Accuracy	92.0%
■ Topological Consistency	81.0%
■ Semantic Completeness	88.0%
■ Source Reliability	90.0%

2. Vertical-Unit Register

Vertical ID	Level	Type	Area (m²)	Usage	Rights	Holder	Status
7A4B9C2D8E1F6G-FB1-UP24-R01	LVL-B1	parking	36.0	vehicle_parking	ownership	Pr**a De*****h	VALID
7A4B9C2D8E1F6G-FB1-UUTIL01-R01	LVL-B1	utility	28.5	electrical_room	common_area	Sh***i He****s So****y	VALID
7A4B9C2D8E1F6G-F00-U001-R01	LVL-00	commercial	120.0	retail_shop	lease	Am*t Ku****i	CONFLICT
7A4B9C2D8E1F6G-F01-U101-R01	LVL-01	residential	95.0	dwelling	ownership	Sn**a Pa**l	CONFLICT
7A4B9C2D8E1F6G-F01-U102-R01	LVL-01	residential	88.5	dwelling	ownership	Ra***h Ku**r Sh***a	CONFLICT
7A4B9C2D8E1F6G-F02-U201-R01	LVL-02	residential	130.0	dwelling	ownership	Me**a Jo**i	VALID
7A4B9C2D8E1F6G-F03-U301-R01	LVL-03	residential	125.0	dwelling	mortgage	Vi***m Si**h Th***r	VALID
7A4B9C2D8E1F6G-F04-U401-R01	LVL-04	residential	160.0	penthouse	ownership	An***a Bh**t	VALID

3. Topology Conflicts

[HIGH] Conflict CONF-001 — boundary_overlap

Conflict Type	boundary_overlap
Conflicting Units	U101, U102
Vertical IDs	7A4B9C2D8E1F6G-F01-U101-R01, 7A4B9C2D8E1F6G-F01-U102-R01
Overlap Area	12.80 m²
Overlap Volume	40.96 m³
Z Overlap Range	4.0 – 7.2 m
Action	Resurvey floor 1 boundary wall between units 101 and 102. Obtain updated BIM/CAD with corrected partition geometry.
Explanation	Units U101 and U102 on Floor 1 share an overlapping boundary strip of 12.8 m² along their common wall. This suggests the partition wall coordinates were recorded with conflicting offsets in the source BIM and cadastral survey datasets.

[MEDIUM] Conflict CONF-002 — encroachment

Conflict Type	encroachment
Conflicting Units	U001, COMMON-GF

Vertical IDs	7A4B9C2D8E1F6G-F00-U001-R01
Overlap Area	4.20 m²
Overlap Volume	16.80 m³
Z Overlap Range	0.0 – 4.0 m
Action	Verify ground-floor commercial unit boundary against approved building plan. Adjust common-area delineation if required.
Explanation	The ground-floor retail unit U001 extends 0.35 m into the designated common corridor area. This likely results from rounding in the original CAD extraction rather than an actual encroachment.

[LOW] Conflict CONF-003 — area_discrepancy

Conflict Type	area_discrepancy
Conflicting Units	UUTIL01
Vertical IDs	7A4B9C2D8E1F6G-FB1-UUTIL01-R01
Overlap Area	0.60 m²
Action	No immediate action required. Flag for next scheduled survey update.
Explanation	Minor area discrepancy of 0.6 m² detected in the basement utility room UUTIL01. Difference is within acceptable tolerance for non-habitable utility spaces but is flagged for completeness.

4. Evidence Sources

Source File	Type	Timestamp	Conf.	SHA-256 (truncated)
shanti_heights_bim_model.ifc	BIM_IFC	2024-11-15T10:30:00+05:30	94%	a3f1b2c4d5e6f708...
cadastral_survey_2024.dxf	CAD_DXF	2024-10-28T14:15:00+05:30	89%	b4e2c3d5a6f70819...
drone_ortho_survey_20241105.tif	drone_survey	2024-11-05T08:45:00+05:30	91%	c5f3d4e6b7a80920...
revenue_records_extract.json	land_record_extract	2024-11-10T16:00:00+05:30	86%	d6a4e5f7c8b91031...

5. QR Verification

Scan the QR code below to verify report authenticity locally.



Report ID: RPT-31BA0439ACCD
ULPIN: 7A4B9C2D8E1F6G
Input SHA-256: 197728d59d773cf6303e23b44c7a0188...