

Model	Part No	Part Name				
4L45W	M015S030	FRM_ASM_2NDC_RH_HALF_UN_(MIX)				
TTD KASIE	TTD OPERATOR	NIK OPERATOR	TAHUN	BULAN	TANGGAL	SHIFT
A	B	C	2025	7	21	1

CHECKED	OK	REPAIR	SCRAP
100	99	1	0

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
1						07
2						77
3						87
4						07
5						08
6						18
7						38
8						28
9						18
10						38
11						68
12						78
13						68
14						68
15	0					08
16						18
17						38
18						68
19						18
20						28
21						68
22						78
23						88
24						98
25						001

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
26						18
27						28
28						38
29						18
30						38
31						38
32						78
33						88
34						08
35						08
36						18
37						28
38						28
39						18
40						28
41						88
42						78
43						68
44						08
45						07
46						17
47						27
48						27
49						17
50						27

FOLDING KERAS	KARAT	DEFORMASI	CAT/COATING	TIDAK MASUK GONOGO	STEP LOSS	STEP LONCAT	STEP LEBIH	STEP KURANG	SALAH PASANG	GORESAN	NOISY	TIDAK LENGKAP
CATATAN:											:WATATAO	