

Model	Part No	Part Name					CHECKED	OK	REPAIR	SCRAP
4L45W	M012S01A	FR_LINK_SUB_ASM_LH					15	12	3	0
TTD KASIE	TTD OPERATOR	NIK OPERATOR	TAHUN	BULAN	TANGGAL	SHIFT				
A	B	C	2025	7	21	1				

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
1						01
2						11
3						01
4						01
5						03
6						18
7	1					08
8						08
9						08
10						08
11						08
12						18
13						08
14						08
15						08
16						10
17						10
18						08
19						10
20						08
21						08
22						10
23						08
24		1				08
25						001

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
26						10
27						08
28						08
29						10
30						08
31						08
32						10
33						08
34						08
35						08
36						10
37						08
38						08
39						10
40						08
41						08
42						10
43						08
44						08
45						01
46						11
47						01
48						01
49						11
50						11

FOLDING KERAS	KARAT	DEFORMASI	CAT/COATING	TIDAK MASUK GONOGO	STEP LOSS	STEP LONCAT	STEP LEBIH	STEP KURANG	SALAH PASANG	GORESAN	NOISY	TIDAK LENGKAP
CATATAN: SALAH											CATATAN:	

PRM-QC-026, rev 3/16 Jul 25

2025-07-21 10:00:00