

Model	Part No	Part Name					CHECKED	OK	REPAIR	SCRAP
5H45	M031T010	FRM_ASM_FB_RH								
TTD KASIE	TTD OPERATOR	NIK OPERATOR	TAHUN	BULAN	TANGGAL	SHIFT				
H	E	1225	2025	09	25	1	212	211	1	

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
1						87
2						77
3						87
4						97
5						08
6						18
7						88
8						88
9						88
10		1				88
11						88
12						78
13						88
14						88
15						00
16						18
17						80
18						80
19						88
20						88
21						88
22						78
23						80
24						88
25						001

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
26						16
27						88
28						88
29						18
30						88
31						88
32						78
33						88
34						08
35						08
36						18
37						88
38						88
39						18
40						88
41						88
42						78
43						88
44						08
45						07
46						17
47						87
48						87
49						17
50						78

FOLDING KERAS	KARAT	DEFORMASI	CAT/COATING	TIDAK MASUK GONOGO	STEP LOSS	STEP LONCAT	STEP LEBIH	STEP KURANG	SALAH PASANG	GORESAN	NOISY	TIDAK LENGKAP
CATATAN:												

FRM-QC-026, rev 3/15 Jul 25