

Model	Part No	Part Name				
5J45	M081T010	FRM_ASM_FB_RH				
TTD KASIE	TTD OPERATOR	NIK OPERATOR	TAHUN	BULAN	TANGGAL	SHIFT
H	A.R	LQK	2025	8	6	2

CHECKED	OK	REPAIR	SCRAP
56	55	1	

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
1						
2						
3						
4						
5						
6						
7						
8						
9			1			
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						

No	KEROPOS	KURANG	BOLONG	UNDERCUT	SPATTER	TIDAK TEPAT
26						
27						
28						
29						
30						
31						
32						
33						
34						
35						
36						
37						
38						
39						
40						
41						
42						
43						
44						
45						
46						
47						
48						
49						
50						

FOLDING KERAS	KARAT	DEFORMASI	CAT/COATING	TIDAK MASUK GONOGO	STEP LOSS	STEP LONCAT	STEP LEBIH	STEP KURANG	SALAH PASANG	GORESAN	NOISY	TIDAK LENGKAP
CATATAN:												

FRM-QC-026, rev 3/15 Jul 25

REVISI