

## Algemeen

**Inspectienummer:** 202503020017  
**Titel:** Check out 204.A | Michal Dobrowolski 700888 | OTTO  
**Locatie:** Lelystad, Maerlant 10  
**Land:** Nederland  
**Provincie:** Flevoland

**Inspectiedatum:** Sun Mar 02 2025

**Geïnspecteerde gebouwen / onderdelen:** 204 LH 6

**Soort inspectie:** regular

**Geïnspecteerd door:** Lelystad - Jakub Wachowski (WO)

**Verantwoordelijke routemanager:** Lelystad - Grzegorz Pastuszka (WO)

**Rapport verstuurd naar:** Labour Housing BV (Germaine55@infodationexample.nl)  
Inspectie Contact Labour Housing 1 (email@example.com)

## Contactpersoon EE-Accommodations

**Telefoonnummer:** +31 (0)85 05 15 990  
**E-mail:** beheer@ee-acco.nl

## Bewonersinformatie

## Samenvatting

**Groene resultaten:** 6/8  
**Gele resultaten:** 2/8  
**Rode resultaten:** 0/8

## Kostensamenvatting

Lelystad, Maerlant 10 / 204 LH 6

### ROOM A

#### Bevindingen

Card not returned Key to bike  
returned 4603 Michal Dobrowolski  
700888 Airkey deactivated

#### Hygiene

#### Bevindingen

Floor not vacuuming, mattress  
dirty from ointment or oil. Lots of  
flaky skin everywhere. The room  
must be cleaned very thoroughly  
before a new resident arrives.

#### Damages

#### Bevindingen

Broken bedside lamp. Mattress  
cover to change it because of  
hygiene. Carpet to change 2m2

#### Omschrijving kosten:

lamp replacement

#### Omschrijving kosten:

mattress cover replacement

#### Omschrijving kosten:

carpet replacement

#### Remarks

#### Bevindingen

Extra cleaning 1 hour. Floor  
vacuumed Room refreshed Cover  
replaced Bedside lamp will be  
replaced in follow up

#### Common Spaces

#### Bevindingen

No visible damages. I noticed the  
tape on the siren fire alarm, it has  
been removed.

#### Toilet/Bathroom

#### Bevindingen

No visible damages.

#### Damages

#### Bevindingen

No visible damages

#### Remarks

#### Bevindingen

-

#### Totaal gefactureerd:

€ 171,17

Gefactureerd aan

Labour Housing BV

Germaine55@infodationexample.nl

## Gedetailleerde inspectiebevindingen

Lelystad, Maerlant 10 / 204 LH 6

### ROOM A


#### Bevindingen



Card not returned Key to bike  
returned 4603 Michal Dobrowolski  
700888 Airkey deactivated



Click [here](#) to view



Click [here](#) to view



Click [here](#) to view




Click [here](#) to view




[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)

---

## Hygiene

Bevindingen



Floor not vacuuming, mattress dirty from ointment or oil. Lots of flaky skin everywhere. The room must be cleaned very thoroughly before a new resident arrives.



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



Click [here](#) to view

### Damages



Bevindingen

Broken bedside lamp. Mattress cover to change it because of hygiene. Carpet to change 2m2

Omschrijving kosten:

lamp replacement

Gefactureerde kosten:

€ 25,00

Omschrijving kosten:

mattress cover replacement

Gefactureerde kosten:


€ 89,17

Omschrijving kosten:

carpet replacement

Gefactureerde kosten:

€ 57,00




Click [here](#) to view




Click [here](#) to view



[Click here to view](#)




[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)

---

#### Remarks

Bevindingen



Extra cleaning 1 hour. Floor  
vacummed Room refreshed Cover


replaced Bedside lamp will be replaced in follow up



[Click here to view](#)




[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)

## Bevindingen


No visible damages. I noticed the tape on the siren fire alarm, it has been removed.



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)




[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)



[Click here to view](#)

---

### Toilet/Bathroom



Bevindingen


No visible damages.




[Click here to view](#)




[Click here to view](#)




[Click here to view](#)




[Click here to view](#)



Click [here](#) to view



Click [here](#) to view



Click [here](#) to view

---

#### Damages



Bevindingen

No visible damages

#### Remarks



Bevindingen

-