

TIME SQUARE 10 SHV REPORT

19 October 2026

TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV ANOTHER POINT OF VIEW



TIME SQUARE 10 SHV FLOOR PLAN




TOOL BOX MEETING







BREAKING PILE-HEAD PROGESS UP TO 19 OCTOBER 2026
178/197pcs




PILECAP FINISHED PROGESS UP TO 19 OCTOBER 2026
22/28pc



BREAKING PILE-HEAD AND COMPLETED PILECAP PROGESS UP TO 19 OCTOBER 2026



SOIL EXCAVATE PC5-6-9







INSTALLING REBAR SEPTIC TANK








INSPECTION REBAR PC9













INSPECTION CONCRETE PC9













INSPECTION FORMWORK COLUMN AND COREWALL BF TO GF








INSPECTION CONCRETE COLUMN AND COREWALL BF TO GF











GROUNDING SYSTERM





SOIL BACKFILL PC12-13







MATERIAL ARRIVED ON SITE







SITE ENVIRONMENT







PASSION FOR PROGRESS!

TIME SQUARE 10

OCEAN VIEW

THE BEST DAY IN OTRES BEACH

THANK YOU!