Weekly Report

09. SEP. 2026

Time Square 11

Project Location

Time Square 11 Point Of View



CBP PROGRESS

CBP PILES (168/168 PILES)



Done
100%



PDA Test Progress

PDA PROGRESS (2/2 Piles)



Done
100%



Time Square 11

Cross-hole Sonic Progress

Up to 09. SEP. 2026 (02/25 Piles)

Sonic Test PROGRESS



Finished Sonic testing.



Time Square 11

Main Pile Progress

Up to 09. SEP. 2026 (09/25 Piles)

Main Pile PROGRESS



Finished Main Pile Concrete.

Unfinished Main Piles.



Drilling Work

Time Square 11

Coordinate Inspection





Time Square 11

Bentonite Inspection



Rebar Inspection

Depth Inspection / Lowering Rebar



Slump Inspection

Time Square 11

Sonic Delivery

Site Cleaning

Time Square 11

Passion For Progress!

Thank You!