Weekly Report

09. OCT. 2026

Time Square 11

Project Location

Time Square 11 Point Of View



CBP PROGRESS

CBP PILES (168/168 PILES)



Done
100%



PDA Test Progress

PDA PROGRESS (2/2 Piles)



Done
100%



Time Square 11

Cross-hole Sonic Progress

Up to 09. Oct. 2026 (02/25 Piles)

Sonic Test PROGRESS



Finished Sonic testing.



Time Square 11

Main Pile Progress

Up to 09. Oct. 2026 (19/25 Piles)

Main Pile PROGRESS



Finished Main Pile Concrete.

Unfinished Main Piles.



Time Square 11

Drilling Work

Coordinate Inspection







Time Square 11

Bentonite Inspection





Time Square 11

Rebar Inspection

Time Square 11

Depth Inspection / Lowering Rebar

Pile Cleaning

Slump Inspection

Casting Concrete



Site Cleaning

Soil Disposal

Time Square 11

Passion For Progress!

Thank You!