

FACTORY MACHINE LOG REPORT

Date: 2024-06-15 | Facility: Industrial Plant Alpha | Report ID: RPT-2024-0615

MACHINE: Conveyor Motor A12

Machine ID: MCH-A12 | Type: Electric Motor | Section A - Production Line 1
Health Score: 58.4/100

Temperature: 84.3 deg C | Vibration: 7.2 mm/s | Pressure: 45.1 PSI
RPM: 1450 | Voltage: 398V | Current: 42.5A
LOG ENTRY: Elevated temperature trend observed over last 72 hours.
Vibration readings exceeding normal threshold 7.2mm/s vs 4.0mm/s baseline.
Bearing noise audible during inspection. Last lubrication: 87 days ago.

MACHINE: Pump B7 Section C

Machine ID: MCH-B7 | Type: Centrifugal Pump | Section C - Cooling Circuit
Health Score: 82.1/100

Temperature: 71.8 deg C | Vibration: 2.1 mm/s | Pressure: 122.4 PSI
RPM: 2950 | Voltage: 401V | Current: 28.3A
LOG ENTRY: Pump operating within normal parameters.
Minor cavitation detected at low flow conditions. Flow rate 98 percent of rated capacity.
Seals inspected 14 days ago OK.

MACHINE: Turbine X9 Section D

Machine ID: MCH-X9 | Type: Steam Turbine | Section D - Power Generation
Health Score: 39.7/100

Temperature: 215.6 deg C | Vibration: 9.8 mm/s | Pressure: 340.2 PSI
RPM: 3000 | Voltage: 11000V | Current: 185.0A
LOG ENTRY: CRITICAL: High vibration detected at rotor stage 2 9.8mm/s.
Thermal imaging shows hot spot on bearing housing. Shaft misalignment suspected.
Multiple alarm triggers in last 24h. Immediate inspection required.

MACHINE: Compressor Unit GH3

Machine ID: MCH-GH3 | Type: Air Compressor | Section B - Utilities
Health Score: 91.0/100

Temperature: 58.2 deg C | Vibration: 1.4 mm/s | Pressure: 8.2 PSI
RPM: 1750 | Voltage: 400V | Current: 18.6A
LOG ENTRY: Air compressor operating normally. Oil level checked adequate.
Filter replaced 12 days ago. Auto-drain functioning correctly.