

# SafeStreet Damage Report Summary

**Location:** 5-1-506, Maharani Jhansi Road, 500095, Hyderabad, Telangana, India

**Summary:** Crack detected. Severity: Medium. Priority: Moderate.

**Status:** Pending

**Date:** 05/06/2025

This report highlights damage at 5-1-506, Maharani Jhansi Road, 500095, Hyderabad, Telangana, India. Summary: Crack detected. Severity: Medium. Priority: Moderate.. Status: Pending.