

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Instrument Calibration Report

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 21659771          |
| Document Number | CAL_EVT-054       |
| Event ID        | EVT-054           |
| Chain ID        | CH-018            |
| Equipment ID    | T-101             |
| Department      | Safety            |
| Generated On    | 15-Jul-2026 14:12 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | CAL_EVT-054  |
| Issue Date      | 14-Jun-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Rahul Sharma |
| Approved By     | Karan Gupta  |
| Status          | Approved     |

#### Calibration Information

|                     |                   |
|---------------------|-------------------|
| Calibration Number  | CAL_-054          |
| Event ID            | EVT-054           |
| Equipment ID        | T-101             |
| Instrument Name     | Raw Material Tank |
| Department          | Safety            |
| Assigned Technician | Rahul Sharma      |
| Status              | Closed            |

#### Equipment Details

|                |                   |
|----------------|-------------------|
| Equipment ID   | T-101             |
| Equipment Name | Raw Material Tank |
| Area           | Tank Farm         |

|                   |                 |
|-------------------|-----------------|
| Department        | Safety          |
| Shift             | Evening         |
| Reported From     | Boiler House    |
| Asset Criticality | High            |
| Failure Category  | Instrumentation |
| Downtime          | 2 Hours         |

Calibration Objective

Calibration check performed for:

T-101

Purpose was to verify instrument accuracy and detect measurement deviation.

Calibration Findings

Calibration findings:

Equipment:

Raw Material Tank

Observed Condition:

Minor spill

Deviation Analysis

Calibration deviation identified.

Possible Cause:

Loose flange

## Adjustment Performed

Adjustment performed.

Corrective Action:

Flange tightened

## Calibration Verification

Post-adjustment verification completed.

Instrument accuracy restored successfully.

## Previous Equipment History

| Event   | Date       | Failure      | Status |
|---------|------------|--------------|--------|
| EVT-024 | 2026-03-16 | Seal failure | Closed |
| EVT-039 | 2026-04-30 | Scheduled    | Closed |
| EVT-054 | 2026-06-14 | Loose flange | Closed |

## Calibration Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☐ Trial Run Successful — Pending

## Recommendations

Check lubrication schedule.

## Linked Documents

- WO\_EVT-054.docx
- MNT\_EVT-054.docx
- INS\_EVT-054.docx
- EMAIL\_EVT-054.txt

## Approval

|             |              |
|-------------|--------------|
| Prepared By | Rahul Sharma |
| Approved By | Karan Gupta  |