

NovaChem Chemicals Pvt. Ltd.

NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,
Vadodara, Gujarat - 390010

Equipment Condition Inspection

Document Information

Document UUID	A3DDA7CC
Document Number	INS_EVT-015
Event ID	EVT-015
Chain ID	CH-005
Equipment ID	B-101
Department	Inspection
Generated On	15-Jul-2026 13:05
Confidentiality	Internal Use Only

Document Control

Document Number	INS_EVT-015
Issue Date	17-Feb-2026
Revision	Rev-1.0
Prepared By	Karan Gupta
Approved By	Anjali Desai
Status	Approved

Equipment Details

Equipment ID	B-101
Equipment Name	Steam Boiler
Area	Utility
Department	Inspection
Shift	Night
Reported From	Field Operator
Asset Criticality	Critical
Failure Category	Instrumentation
Downtime	0 Hours

Inspection Objective

Inspection initiated following an operational complaint from Inspection.

Inspection Findings

Equipment checked for vibration, temperature, leakage and alignment.

Status :

Closed

Observed Defects

Inspector observed:

Boiler emergency drill

Risk Assessment

Risk Level : Medium

Inspector Remarks

Preventive maintenance interval should be reduced.

Safety Observation

Equipment was electrically isolated before repair.

Inspection Tools

Insulation Tester

Inspection Summary

Priority	High
Severity	Low
Status	Closed

Downtime	0 Hours
Follow-up Required	Yes
Asset Criticality	Critical

Previous Equipment History

Event	Date	Failure	Status
EVT-011	2026-02-05	Scale buildup	Closed
EVT-012	2026-02-08	Follow-up	Closed
EVT-013	2026-02-11	Routine	Closed
EVT-014	2026-02-14	Follow-up	Closed
EVT-015	2026-02-17	Scheduled	Closed

Root Cause

Scheduled

Inspection Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☒ Trial Run Successful

Recommendations

Perform vibration analysis after one week.

Linked Documents

- WO_EVT-015.docx
- MNT_EVT-015.docx
- INS_EVT-015.docx
- EMAIL_EVT-015.txt

Approval

Prepared By	Karan Gupta
Approved By	Anjali Desai