

# NovaChem Chemicals Pvt. Ltd.

## NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,  
Vadodara, Gujarat - 390010

### Detailed Equipment Inspection

#### Document Information

|                 |                   |
|-----------------|-------------------|
| Document UUID   | 574D8728          |
| Document Number | INS_EVT-029       |
| Event ID        | EVT-029           |
| Chain ID        | CH-010            |
| Equipment ID    | TG-101            |
| Department      | Maintenance       |
| Generated On    | 15-Jul-2026 13:05 |
| Confidentiality | Internal Use Only |

#### Document Control

|                 |              |
|-----------------|--------------|
| Document Number | INS_EVT-029  |
| Issue Date      | 31-Mar-2026  |
| Revision        | Rev-1.0      |
| Prepared By     | Karan Gupta  |
| Approved By     | Suresh Kumar |
| Status          | Approved     |

#### Equipment Details

|                   |                   |
|-------------------|-------------------|
| Equipment ID      | TG-101            |
| Equipment Name    | Temperature Gauge |
| Area              | Reactor Area      |
| Department        | Maintenance       |
| Shift             | Morning           |
| Reported From     | Control Room      |
| Asset Criticality | Medium            |
| Failure Category  | Instrumentation   |
| Downtime          | 6 Hours           |

## Inspection Objective

Detailed inspection performed after maintenance completion.

## Inspection Findings

Inspection verified that corrective action has been completed.

Asset Criticality :

Medium

## Observed Defects

Verification Remarks:

Calibrated

## Risk Assessment

Risk Level : Low

## Inspector Remarks

Recommend vibration monitoring during next inspection.

## Safety Observation

Equipment was electrically isolated before repair.

## Inspection Tools

Hydraulic Jack

## Inspection Summary

|          |        |
|----------|--------|
| Priority | Medium |
| Severity | Low    |
| Status   | Closed |

|                    |         |
|--------------------|---------|
| Downtime           | 6 Hours |
| Follow-up Required | No      |
| Asset Criticality  | Medium  |

### Previous Equipment History

| Event   | Date       | Failure | Status |
|---------|------------|---------|--------|
| EVT-029 | 2026-03-31 | Routine | Closed |

### Root Cause

Routine

### Inspection Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☒ Trial Run Successful

### Recommendations

Replace similar components during annual shutdown.

### Linked Documents

- WO\_EVT-029.docx
- MNT\_EVT-029.docx
- INS\_EVT-029.docx
- EMAIL\_EVT-029.txt

Approval

|             |              |
|-------------|--------------|
| Prepared By | Karan Gupta  |
| Approved By | Suresh Kumar |