

NovaChem Chemicals Pvt. Ltd.

NovaChem Industrial Plant

Plot No. 18, GIDC Industrial Estate,
Vadodara, Gujarat - 390010

Routine Inspection Report

Document Information

Document UUID	D0A15FDE
Document Number	INS_EVT-037
Event ID	EVT-037
Chain ID	CH-013
Equipment ID	CT-101
Department	Inspection
Generated On	15-Jul-2026 13:05
Confidentiality	Internal Use Only

Document Control

Document Number	INS_EVT-037
Issue Date	24-Apr-2026
Revision	Rev-1.0
Prepared By	Pooja Mehta
Approved By	Anjali Desai
Status	Approved

Equipment Details

Equipment ID	CT-101
Equipment Name	Cooling Tower
Area	Utility
Department	Inspection
Shift	Morning
Reported From	Field Operator
Asset Criticality	Medium
Failure Category	Instrumentation
Downtime	0 Hours

Inspection Objective

Routine inspection was conducted on Cooling Tower to evaluate its operating condition and identify any abnormalities.

Inspection Findings

Inspection completed successfully.

Failure Category :
Instrumentation

Severity :
Low

Equipment condition appears satisfactory.

Observed Defects

Observed condition:

Instrument calibration

Risk Assessment

Risk Level : Low

Inspector Remarks

Further monitoring is recommended before closing the case.

Safety Observation

LOTO procedure was followed throughout maintenance.

Inspection Tools

Torque Wrench

Inspection Summary

Priority	Low
Severity	Low
Status	Closed
Downtime	0 Hours
Follow-up Required	No
Asset Criticality	Medium

Previous Equipment History

Event	Date	Failure	Status
EVT-022	2026-03-10	Loose flange	Closed
EVT-037	2026-04-24	Routine	Closed

Root Cause

Routine

Inspection Checklist

- ☒ Lock Out / Tag Out (LOTO) Followed
- ☒ PPE Worn
- ☒ Visual Inspection Completed
- ☒ Lubrication Checked
- ☒ Leak Inspection Completed
- ☒ Alignment Verified
- ☒ Trial Run Successful

Recommendations

Conduct thermography inspection next month.

Linked Documents

- WO_EVT-037.docx
- MNT_EVT-037.docx
- INS_EVT-037.docx

- EMAIL_EVT-037.txt

Approval

Prepared By	Pooja Mehta
Approved By	Anjali Desai