



Market & Factory Surveillance Directory

This surveillance directory is a synthetic demonstration dataset for BIS MITRA. All identifiers, organizations, locations, test references, notices, orders and case outcomes are fictional. The records are structured to support retrieval, source citation, filtering and follow-up questions.

Demo Id	Surveillance Date	Surveillance Type	Risk Level	Current Status
SURV-DEMO-001	2026-09-26	Routine Market Surveillance	High	Referred to Enforcement - ENF-DEMO-001
SURV-DEMO-002	2026-09-26	High-Risk Factory Surveillance	High	Referred to Enforcement - ENF-DEMO-002
SURV-DEMO-003	2026-09-26	Routine Market Surveillance	High	Referred to Enforcement - ENF-DEMO-003
SURV-DEMO-004	2026-09-25	Factory Surveillance	Medium	Referred to Enforcement - ENF-DEMO-004
SURV-DEMO-005	2026-09-25	Routine Market Surveillance	Medium	Completed - observation closed
SURV-DEMO-006	2026-09-24	High-Risk Factory Surveillance	High	Compliance Alert - Emergency Enforcement Review
SURV-DEMO-007	2026-09-24	Routine Factory Surveillance	Medium	Completed
SURV-DEMO-008	2026-09-23	Market Surveillance	High	Referred to Enforcement - ENF-DEMO-009
SURV-DEMO-009	2026-09-23	Market Surveillance	High	Referred to Enforcement - ENF-DEMO-010
SURV-DEMO-010	2026-09-22	Routine Market Surveillance	Medium	Pending Laboratory Result
SURV-DEMO-011	2026-09-21	Factory Surveillance	High	Completed - corrective action verified
SURV-DEMO-012	2026-09-20	Routine Market Surveillance	High	Referred to Enforcement - ENF-DEMO-012
SURV-DEMO-013	2026-09-18	Follow-up Surveillance	High	Follow-up Completed
SURV-DEMO-014	2026-09-17	Routine Market Surveillance	Medium	Completed - Alert Monitoring Continued

Record 01: SURV-DEMO-001

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-001

Surveillance ID	SURV-DEMO-001
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-26
Product	Industrial Safety Helmet - ASW-H7
Product category	Personal Protective Equipment
Manufacturer	Aarohan Safety Works Pvt. Ltd. (Synthetic)
Location	Pimpri Wholesale Market
State	Maharashtra
Standard number	IS DEMO 1001:2026
QCO reference	QCO DEMO 001:2026
Licence number	LIC-DEMO-26001
Sample ID	SAMP-DEMO-001
Sample quantity	6 helmets
Sampling location	Retailer cluster RCL-DEMO-PN-01
Risk level	High
Test required	Impact absorption; penetration; retention screening
Laboratory	LAB-DEMO-006 - Suraksha Head Protection Lab (Synthetic)
Test report reference	TR-DEMO-001
Test result	Failed - crown impact absorption below synthetic criterion.
Compliance status	Non-compliant
Finding	Sample failed impact absorption; traceability code also differed across two sampled cartons.
Alert reference	ALT-DEMO-001
Assigned office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-S01
Follow-up required	Yes
Follow-up date	2026-10-03
Current status	Referred to Enforcement - ENF-DEMO-001
Keywords	helmet surveillance; failed impact; high risk; market
Synonyms	safety helmet monitoring; PPE surveillance; failed helmet sample
Enforcement case reference	ENF-DEMO-001

Record 02: SURV-DEMO-002

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-002

Surveillance ID	SURV-DEMO-002
Surveillance type	High-Risk Factory Surveillance
Surveillance date	2026-09-26
Product	Domestic Induction Cooking Appliance - BRH-IC2
Product category	Electrical Appliances
Manufacturer	BlueRiver Home Appliances (Synthetic)
Location	Sriperumbudur Appliance Park
State	Tamil Nadu
Standard number	IS DEMO 1003:2025
QCO reference	QCO DEMO 003:2026
Licence number	LIC-DEMO-26003
Sample ID	SAMP-DEMO-002
Sample quantity	4 appliances
Sampling location	Final Inspection Bay - FIB-DEMO-CH-02
Risk level	High
Test required	Dielectric withstand; earth continuity; leakage current; temperature rise
Laboratory	LAB-DEMO-001 - ApexLab Industrial Testing Centre (Synthetic)
Test report reference	TR-DEMO-002
Test result	Failed - dielectric withstand below synthetic requirement.
Compliance status	Non-compliant
Finding	Two units failed dielectric withstand; process logs showed repeat variation in the same lot.
Alert reference	ALT-DEMO-002
Assigned office	BIS MITRA Demo Office - Chennai
Officer reference	OFF-DEMO-CH-S02
Follow-up required	Yes
Follow-up date	2026-10-05
Current status	Referred to Enforcement - ENF-DEMO-002
Keywords	induction appliance; electrical safety; high risk; failed sample
Synonyms	cooker surveillance; electrical appliance monitoring; insulation failure
Enforcement case reference	ENF-DEMO-002

Record 03: SURV-DEMO-003

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-003

Surveillance ID	SURV-DEMO-003
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-26
Product	Flexible Food Pouch - FP-21
Product category	Food and Packaging
Manufacturer	FreshFold Packaging Works (Synthetic)
Location	Whitefield Retail Cluster
State	Karnataka
Standard number	IS DEMO 1002:2025
QCO reference	QCO DEMO 002:2026
Licence number	-
Sample ID	SAMP-DEMO-003
Sample quantity	12 pouches
Sampling location	Distributor DC-DEMO-BL-03
Risk level	High
Test required	Food-contact migration; material identification; marking review
Laboratory	LAB-DEMO-003 - NutriSure Food Contact Analytics Lab (Synthetic)
Test report reference	TR-DEMO-003
Test result	Failed - migration above synthetic threshold; marking review also failed.
Compliance status	Non-compliant
Finding	Food-contact migration failure confirmed in the synthetic lab record.
Alert reference	ALT-DEMO-003
Assigned office	BIS MITRA Demo Office - Bengaluru
Officer reference	OFF-DEMO-BL-S03
Follow-up required	Yes
Follow-up date	2026-10-02
Current status	Referred to Enforcement - ENF-DEMO-003
Keywords	food pouch; migration; market surveillance; compliance alert
Synonyms	food packaging monitoring; pouch surveillance; migration failure
Enforcement case reference	ENF-DEMO-003

Record 04: SURV-DEMO-004

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-004

Surveillance ID	SURV-DEMO-004
Surveillance type	Factory Surveillance
Surveillance date	2026-09-25
Product	Cementitious Repair Mortar - NSR-M25
Product category	Construction Materials
Manufacturer	NirmanSet Repair Materials LLP (Synthetic)
Location	Demo Repair Materials Estate
State	Maharashtra
Standard number	IS DEMO 1004:2024
QCO reference	QCO DEMO 004:2025
Licence number	LIC-DEMO-26004
Sample ID	SAMP-DEMO-004
Sample quantity	6 bags
Sampling location	Production Line 2 - PL2-DEMO-PN
Risk level	Medium
Test required	Compressive strength; bond strength; density
Laboratory	LAB-DEMO-004 - BuildMet Mechanical & Fire Materials Lab (Synthetic)
Test report reference	TR-DEMO-004
Test result	Failed - compressive strength below synthetic criterion.
Compliance status	Non-compliant
Finding	One production shift yielded low compressive-strength result.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-S04
Follow-up required	Yes
Follow-up date	2026-10-01
Current status	Referred to Enforcement - ENF-DEMO-004
Keywords	repair mortar; strength failure; construction surveillance
Synonyms	mortar surveillance; construction material monitoring; strength test
Enforcement case reference	ENF-DEMO-004

Record 05: SURV-DEMO-005

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-005

Surveillance ID	SURV-DEMO-005
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-25
Product	LED Road Luminaire - PRL-R120
Product category	Lighting
Manufacturer	PrabhaRoad Illumination Systems Ltd. (Synthetic)
Location	Municipal Lighting Store Cluster
State	Tamil Nadu
Standard number	IS DEMO 1005:2026
QCO reference	QCO DEMO 005:2026
Licence number	LIC-DEMO-26005
Sample ID	SAMP-DEMO-005
Sample quantity	3 luminaires
Sampling location	Road Lighting Stockyard RLS-DEMO-CH
Risk level	Medium
Test required	Photometry; electrical input; power factor; environmental conditioning
Laboratory	LAB-DEMO-005 - LumaVolt Lighting Performance Lab (Synthetic)
Test report reference	TR-DEMO-005
Test result	Passed - all sampled parameters within synthetic requirements; one packaging seal noted for correction.
Compliance status	Compliant with observation
Finding	Performance tests passed; minor packaging seal observation recorded.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Chennai
Officer reference	OFF-DEMO-CH-S05
Follow-up required	No
Follow-up date	-
Current status	Completed - observation closed
Keywords	LED surveillance; lighting; passed sample; market
Synonyms	road luminaire monitoring; lighting surveillance; photometry check
Enforcement case reference	ENF-DEMO-007

Record 06: SURV-DEMO-006

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-006

Surveillance ID	SURV-DEMO-006
Surveillance type	High-Risk Factory Surveillance
Surveillance date	2026-09-24
Product	LPG Cabinet Heater - UHD-4K
Product category	Gas Appliances
Manufacturer	Ujjwal Hearth Devices Pvt. Ltd. (Synthetic)
Location	Demo Gas Appliance Zone
State	Rajasthan
Standard number	IS DEMO 1007:2025
QCO reference	QCO DEMO 007:2026
Licence number	LIC-DEMO-26007
Sample ID	SAMP-DEMO-006
Sample quantity	3 heaters
Sampling location	Assembly Line A - AL-DEMO-JP
Risk level	High
Test required	Gas leakage; combustion; flame stability; safety shut-off
Laboratory	LAB-DEMO-007 - AgniSafe Gas Appliance Test House (Synthetic)
Test report reference	TR-DEMO-006
Test result	Failed - gas leakage detected at regulator connection.
Compliance status	Non-compliant
Finding	Leak rate exceeded synthetic acceptance criterion.
Alert reference	ALT-DEMO-004
Assigned office	BIS MITRA Demo Office - Jaipur
Officer reference	OFF-DEMO-JP-S06
Follow-up required	Yes
Follow-up date	2026-09-29
Current status	Compliance Alert - Emergency Enforcement Review
Keywords	LPG heater; gas leak; high risk; surveillance alert
Synonyms	gas appliance surveillance; heater leak monitoring; emergency safety alert
Enforcement case reference	ENF-DEMO-006

Record 07: SURV-DEMO-007

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-007

Surveillance ID	SURV-DEMO-007
Surveillance type	Routine Factory Surveillance
Surveillance date	2026-09-24
Product	Modular Office Chair - KOF-M8
Product category	Furniture
Manufacturer	Kshetra Office Furnishings Co. (Synthetic)
Location	Demo Furniture Manufacturing Park
State	Haryana
Standard number	IS DEMO 1008:2024
QCO reference	QCO DEMO 008:2024
Licence number	LIC-DEMO-26008
Sample ID	SAMP-DEMO-007
Sample quantity	2 chairs
Sampling location	Finished Goods Area FGA-DEMO-GR
Risk level	Medium
Test required	Static strength; fatigue cycling; stability
Laboratory	LAB-DEMO-010 - Precision Furniture & Consumer Durability Lab (Synthetic)
Test report reference	TR-DEMO-007
Test result	Passed - sampled units met synthetic durability requirements.
Compliance status	Compliant
Finding	Routine surveillance sample passed all selected tests.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Gurugram
Officer reference	OFF-DEMO-GR-S07
Follow-up required	No
Follow-up date	-
Current status	Completed
Keywords	office chair; routine surveillance; passed sample
Synonyms	furniture monitoring; chair surveillance; durability screening
Enforcement case reference	ENF-DEMO-008

Record 08: SURV-DEMO-008

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-008

Surveillance ID	SURV-DEMO-008
Surveillance type	Market Surveillance
Surveillance date	2026-09-23
Product	Rooftop Solar PV Mounting System - SGM-RF2
Product category	Renewable Energy
Manufacturer	SuryaGrid Mounting Systems Pvt. Ltd. (Synthetic)
Location	Demo Solar Hardware Market
State	Gujarat
Standard number	IS DEMO 1009:2026
QCO reference	QCO DEMO 009:2026
Licence number	LIC-DEMO-26009
Sample ID	SAMP-DEMO-008
Sample quantity	2 mounting kits
Sampling location	Distributor Yard DY-DEMO-AH
Risk level	High
Test required	Joint integrity; fastener pull-out; corrosion screening
Laboratory	LAB-DEMO-009 - RenewGrid Solar Structures Test Lab (Synthetic)
Test report reference	TR-DEMO-008
Test result	Failed - fastener pull-out below synthetic requirement.
Compliance status	Non-compliant
Finding	One sampled configuration failed pull-out test.
Alert reference	ALT-DEMO-005
Assigned office	BIS MITRA Demo Office - Ahmedabad
Officer reference	OFF-DEMO-AH-S08
Follow-up required	Yes
Follow-up date	2026-09-30
Current status	Referred to Enforcement - ENF-DEMO-009
Keywords	solar mounting; failed sample; high risk; surveillance
Synonyms	PV structure monitoring; solar hardware surveillance; fastener failure
Enforcement case reference	ENF-DEMO-009

Record 09: SURV-DEMO-009

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-009

Surveillance ID	SURV-DEMO-009
Surveillance type	Market Surveillance
Surveillance date	2026-09-23
Product	Stainless Steel Food-Contact Utensils - SKI ProLine Set
Product category	Food-Contact Materials
Manufacturer	Sampoorna Kitchenware Industries (Synthetic)
Location	Demo Kitchenware Bazaar
State	Kerala
Standard number	IS DEMO 1006:2025
QCO reference	QCO DEMO 006:2025
Licence number	LIC-DEMO-26006
Sample ID	SAMP-DEMO-009
Sample quantity	4 utensil sets
Sampling location	Retail Shelf RS-DEMO-KO-09
Risk level	High
Test required	Elemental screening; extractables; hygiene-related surface checks
Laboratory	LAB-DEMO-003 - NutriSure Food Contact Analytics Lab (Synthetic)
Test report reference	TR-DEMO-009
Test result	Failed - elemental migration above synthetic criterion.
Compliance status	Non-compliant
Finding	One contact-metal sample showed elevated migration.
Alert reference	ALT-DEMO-006
Assigned office	BIS MITRA Demo Office - Kochi
Officer reference	OFF-DEMO-KO-S09
Follow-up required	Yes
Follow-up date	2026-09-28
Current status	Referred to Enforcement - ENF-DEMO-010
Keywords	utensils; food contact; migration; failed sample
Synonyms	kitchenware surveillance; stainless utensil monitoring; metal migration
Enforcement case reference	ENF-DEMO-010

Record 10: SURV-DEMO-010

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-010

Surveillance ID	SURV-DEMO-010
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-22
Product	uPVC Drainage Pipe - UD-110
Product category	Construction Materials
Manufacturer	PipeNova Drainage Systems (Synthetic)
Location	Demo Building Materials Market
State	Gujarat
Standard number	IS DEMO 1011:2026
QCO reference	QCO DEMO 011:2026
Licence number	-
Sample ID	SAMP-DEMO-010
Sample quantity	10 pipe lengths
Sampling location	Distributor Stockyard DS-DEMO-AH-10
Risk level	Medium
Test required	Dimensional checks; water absorption; pressure/rigidity screening
Laboratory	LAB-DEMO-002 - Sahaya Materials Evaluation Lab (Synthetic)
Test report reference	TR-DEMO-010-PENDING
Test result	Pending - laboratory report not yet issued.
Compliance status	Pending Test Result
Finding	Sample collected for wall-thickness and material checks; final report pending.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Ahmedabad
Officer reference	OFF-DEMO-AH-S10
Follow-up required	Yes
Follow-up date	2026-09-30
Current status	Pending Laboratory Result
Keywords	uPVC pipe; pending test; construction surveillance
Synonyms	drainage pipe monitoring; pipe sample; pending lab result
Enforcement case reference	ENF-DEMO-005

Record 11: SURV-DEMO-011

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-011

Surveillance ID	SURV-DEMO-011
Surveillance type	Factory Surveillance
Surveillance date	2026-09-21
Product	Electric Storage Water Heater - HSA-E25
Product category	Electrical Appliances
Manufacturer	HydroSafe Appliances (Synthetic)
Location	Demo Appliance Park, Pune
State	Maharashtra
Standard number	IS DEMO 1014:2025
QCO reference	QCO DEMO 012:2026
Licence number	LIC-DEMO-26010
Sample ID	SAMP-DEMO-011
Sample quantity	3 heaters
Sampling location	Final Test Bay FTB-DEMO-PN-11
Risk level	High
Test required	Temperature rise; thermal cut-off; leakage current; insulation
Laboratory	LAB-DEMO-001 - ApexLab Industrial Testing Centre (Synthetic)
Test report reference	TR-DEMO-011
Test result	Passed - corrective-action verification sample met synthetic requirements.
Compliance status	Compliant - Corrective Action Verified
Finding	Follow-up surveillance confirmed previous thermal cut-off correction.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Pune
Officer reference	OFF-DEMO-PN-S11
Follow-up required	No
Follow-up date	-
Current status	Completed - corrective action verified
Keywords	water heater surveillance; corrective action; passed sample
Synonyms	geyser monitoring; heater follow-up surveillance; thermal cut-off check
Enforcement case reference	ENF-DEMO-011

Record 12: SURV-DEMO-012

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-012

Surveillance ID	SURV-DEMO-012
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-20
Product	Industrial Safety Helmet - ASW-H9
Product category	Personal Protective Equipment
Manufacturer	Aarohan Safety Works Pvt. Ltd. (Synthetic)
Location	Demo Hardware Market, Lucknow
State	Uttar Pradesh
Standard number	IS DEMO 1001:2026
QCO reference	QCO DEMO 001:2026
Licence number	LIC-DEMO-26002
Sample ID	SAMP-DEMO-012
Sample quantity	6 helmets
Sampling location	Distributor Yard DY-DEMO-LK-12
Risk level	High
Test required	Retention; impact; penetration
Laboratory	LAB-DEMO-006 - Suraksha Head Protection Lab (Synthetic)
Test report reference	TR-DEMO-012
Test result	Failed - retention force below synthetic threshold.
Compliance status	Non-compliant
Finding	Two samples failed retention system test.
Alert reference	-
Assigned office	BIS MITRA Demo Office - Lucknow
Officer reference	OFF-DEMO-LK-S12
Follow-up required	Yes
Follow-up date	2026-10-01
Current status	Referred to Enforcement - ENF-DEMO-012
Keywords	helmet; retention; failed sample; market surveillance
Synonyms	PPE monitoring; chin strap surveillance; helmet sample failure
Enforcement case reference	ENF-DEMO-012

Record 13: SURV-DEMO-013

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-013

Surveillance ID	SURV-DEMO-013
Surveillance type	Follow-up Surveillance
Surveillance date	2026-09-18
Product	LPG Cabinet Heater - UHD-4K
Product category	Gas Appliances
Manufacturer	Ujjwal Hearth Devices Pvt. Ltd. (Synthetic)
Location	Demo Gas Appliance Zone, Jaipur
State	Rajasthan
Standard number	IS DEMO 1007:2025
QCO reference	QCO DEMO 007:2026
Licence number	LIC-DEMO-26007
Sample ID	SAMP-DEMO-013
Sample quantity	3 heaters
Sampling location	Reworked Finished Goods Area RFGA-DEMO-JP
Risk level	High
Test required	Gas leakage; combustion; flame stability; safety shut-off
Laboratory	LAB-DEMO-007 - AgniSafe Gas Appliance Test House (Synthetic)
Test report reference	TR-DEMO-013
Test result	Passed - verification samples met synthetic gas-safety criteria.
Compliance status	Compliant - Follow-up Passed
Finding	Reworked lot passed after emergency sealing and corrective action.
Alert reference	ALT-DEMO-004
Assigned office	BIS MITRA Demo Office - Jaipur
Officer reference	OFF-DEMO-JP-S13
Follow-up required	No
Follow-up date	-
Current status	Follow-up Completed
Keywords	LPG heater; follow-up; passed; alert closure
Synonyms	gas appliance follow-up; heater re-test; safety alert closure
Enforcement case reference	ENF-DEMO-014

Record 14: SURV-DEMO-014

Source citation: BIS MITRA Demo -> Surveillance -> SURV-DEMO-014

Surveillance ID	SURV-DEMO-014
Surveillance type	Routine Market Surveillance
Surveillance date	2026-09-17
Product	Flexible Food Pouch - FP-21
Product category	Food and Packaging
Manufacturer	FreshFold Packaging Works (Synthetic)
Location	Demo Food Packaging Market, Bengaluru
State	Karnataka
Standard number	IS DEMO 1002:2025
QCO reference	QCO DEMO 002:2026
Licence number	-
Sample ID	SAMP-DEMO-014
Sample quantity	12 pouches
Sampling location	Retail Shelf RS-DEMO-BL-14
Risk level	Medium
Test required	Migration screening; marking review
Laboratory	LAB-DEMO-003 - NutriSure Food Contact Analytics Lab (Synthetic)
Test report reference	TR-DEMO-014
Test result	Passed - replacement batch met synthetic screening criteria.
Compliance status	Compliant
Finding	Follow-up sample from corrected material batch passed screening.
Alert reference	ALT-DEMO-003
Assigned office	BIS MITRA Demo Office - Bengaluru
Officer reference	OFF-DEMO-BL-S14
Follow-up required	No
Follow-up date	-
Current status	Completed - Alert Monitoring Continued
Keywords	food pouch; passed sample; surveillance; alert
Synonyms	packaging follow-up; food-contact surveillance; pouch compliance
Enforcement case reference	ENF-DEMO-003

Demo note

Use the demo_id, case IDs, inspection IDs, laboratory IDs, standard numbers, QCO references and licence numbers as stable synthetic identifiers for MITRA retrieval and source citation.