ARYADI BUSINESS PVT.LTD.

SERVICE REPORT

FIELD SERVICE REPORT

ISO 9001:2015 | ISO 14001:2015 | ISO 45001:2018 Certified

REPORT NUMBER	TICKET NO	REGISTERED ON	CLOSED ON
ARYADI-SR-32390	**CS-RM-062833**	**2026-07-11 11:31:24**	**2026-07-11 18:26:16**

Customer Details

Customer Name	BHARTI AIRTEL
Branch Name	BA - Tilak Road PUN-ROM MH
Address	SHOP NO 4 SHIVANANDAN CHS OPP MAHARASHTRA MANDAL SADAVSHIV PETH TILAK ROAD PUNE 411030
Mobile No.	8484000384
Client Ticket No.	—

Service Ticket Details

Type	R&M
Service	Painting
Sub Service	Full Store Paint
Status	Closed
Attended Date	2026-07-11
Attended Location	—

Service Details

PROBLEM STATEMENT

all Dismantle work and wall/ceiling repairing and paint quotation required

TECHNICIAN / ENGINEER OBSERVATION

painting 1750sqft

ACTION TAKEN

painting 1750sqft

TECHNICIAN / ENGINEER REMARKS

close

Line Items Used

#	ITEM & DESCRIPTION	ARC	HSN/SAC	UOM	QTY
1	charges forPainting work at site repairing of wall and ceiling repair	N.A.	998717	SQFT	1750

Turnaround Time

TOTAL TIME	=	WORK ACCEPT	+	QUOTATION TIME	+	WORK TIME	+	VERIFY TIME
6 h 54 m 52 s Closed - Raised		**6 h 53 m 49 s** Work Start - Raised		**5 h 36 m 53 s** Approved - Sent		**1 m 3 s** Closed - Work Start		**1 m 21 s** OTP - Closed

Pre Image(s)

0 PHOTO(S)

No pre-work images captured.

Post Image(s)

0 PHOTO(S)

No post-work images captured.

Activity Log

#	STATUS	ASSIGNED TO	UPDATED BY	DATE	TIME
1	**Raised**	—	Rupali	2026-07-11	11:31:24
2	**Assigned**	—	Rupali	2026-07-11	11:35:11
3	**Assigned**	—	Rupali	2026-07-11	11:35:38
4	**Quote Sent Approval Pending**	—	—	2026-07-11	11:42:52
5	**Quote Approved**	—	—	2026-07-11	17:19:45
6	**Generate OTP to Start**	—	amit.dhage	2026-07-11	18:24:55
7	**Work In Progress**	—	—	2026-07-11	18:25:13
8	**Generate OTP to Close**	—	amit.dhage	2026-07-11	18:26:02
9	**Generate OTP to Close**	—	amit.dhage	2026-07-11	18:26:03
10	**Closed**	—	—	2026-07-11	18:26:16

Technician Safety Checklist

#	CHECKLIST ITEM	STATUS	IMAGE
1	Am i wearing the company uniform?	**NO**	No image
2	Am i wearing a safety jacket?	**NO**	No image
3	Do i have an Insulated toolkit?	**NO**	No image
4	Am i wearing safety shoes?	**NO**	No image
5	Do i have the PPE kit?	**NO**	No image

Acknowledgement

Technician Details

Name —

Phone Number —

Authorised Signatory

Onsite Client Representative (Verified By)

Name Santosh Gavali

Designation —

Contact Number 8484000384

2026-07-11 18:25:39