



SERVICE REPORT

Tel.: +971 6 741 2778
Fax: +971 6 741 2595
P.O. Box: 7777, Ajman, UAE
e-mail: info@amaanajh.com
Website: www.amaanajh.com

SRN: **FS-TEST-GM-0001**

Customer GM Workflow Test Tower		Job No FS-TEST-GM-0001	Page 1 of 1	
		Site Name GM Workflow Test Tower	Location	
Engineer / Technician Arshith Technician		Date 20 Jul 2026		
Fire Alarm System				
Qty	Type		Time Arrive	Hrs
			Time Left	Hrs
			Travel Time	Hrs
Make	No. of Zones / Loops		Total	Hrs
				00
				Mns
				00

Fire Fighting System		Type of Job Fire Systems Inspection	
Fire Extinguisher	☐ Gas Suppression	☐ PPM	☐
Hose Reel	☐ Kitchen Hood	☐ Inspection	☒
Sprinkler	☐ Wet / Dry Riser	☐ Rectification	☐
Fire Pump Set	☐ Others	☐ Others	☐

Comments:

HVAC / Chiller Unit 2: Chiller with partial load test — Minor vibration observed, recommended monitoring.

HVAC / AHU-05: Air Handling Unit - Level 5 — Filters replaced, differential pressure within limits.

Supervisor: Inspection completed. Minor issues noted, safe to operate.

Parts Used	Specification	Qty	Parts Required	Specification	Qty

Customer Remarks:

Customer Name : GM Workflow Test Tower	Engineer/Technician Name: Arshith Technician
Mobile No:	ID No:

Fire Systems Inspection — Attachments & Approvals

Site: GM Workflow Test Tower

Inspection Photos

2 photo(s)

Chiller Unit 2

AHU-05

Approval Signatures

Supervisor	
Comments	Inspection completed. Minor issues noted, safe to operate.
Signature	

Operations Manager	
Comments	Agree with supervisor assessment. Schedule follow-up in 30 days.
Signature	

Business Development	
Comments	No commercial impact foreseen at this stage.
Signature	

Procurement	
Comments	Spare parts quotation to be requested only if vibration worsens.
Signature	

General Manager	
Comments	Approved. Proceed as per Operations Manager plan.
Signature	