


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 14:16:58.098643


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-113-_jpg.rf.488cacc48d48994083f3f60bd84b1088.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System