


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:56:22.817057


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-132-_jpg.rf.51deec71931b9582fe982d041f5f45e1.jpg



Severity: HIGH

Defects: 2 cracks detected

Generated by AeroInspect AI System