


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:33:30.226018

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-224-_jpg.rf.830165b4bdf8d3b28483ed9ef8787ff3.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System