


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 12:04:51.320705

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-245-[_jpg.rf.dc967a69da4370e74b62b07c27ddc9a1.jpg](#)



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System