


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-09 20:13:14.438436

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-3-_jpg.rf.18946519ef58ad8c20efcaaedcd8d7ec.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System