


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-05 21:32:14.919445


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-303-_jpg.rf.8f0b8253391f5cb4ab770b0f7b576843.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System