


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-11 19:53:18.513976

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-354-_jpg.rf.8abba1f4db0824c5fab82e8c4355fe8.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System