


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:50:29.363587

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-45-_jpg.rf.5b1841d7657d542afa089cdaf77008ae.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System