


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 12:25:43.101638

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-451-_jpg.rf.fe5e1a37e4f3f1968ed71c81ff29673d.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System