


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:17:27.061770

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-472-_jpg.rf.0cf9b7f144258dc86b737a8f817b1bc3.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System