


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-11 19:53:53.961957


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-482-[_jpg.rf.23dff19075e1d28293a97866b37be791.jpg](#)



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System