


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-09 20:01:44.708548

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-52-.jpg.rf.212e12c37201c65dc6c47a3a7e019d3c.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System