


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:22:06.601805

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-520-[_jpg.rf.ab277d84e0c98693453e2c41ef579300.jpg](#)



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System