


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-11 19:53:58.657160


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-531-_.jpg.rf.79e57b5c6e79e3f951ec7b05edcdf913.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System