


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 13:55:10.452907

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-547-_jpg.rf.a28e6e93fbd7b2ba32f0068d86f9c572.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System