


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-09 19:51:23.605449

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-55-.jpg.rf.ab39e4212a3436e6fcc0b4cd72572001.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System