


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 12:57:43.158309

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-551-_jpg.rf.109612ed6b12013a45c945c8e2983b5e.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System