


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-07 10:14:21.677769


Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-581-_jpg.rf.d98b45ac0588b67b6d22dc8250033a1d.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System