


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-12 14:24:53.460864

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



crack-609-_jpg.rf.617da9d7a40e3230a51cb7272e088c1c.jpg



Severity: HIGH

Defects: 1 cracks detected

Generated by AeroInspect AI System