


AeroInspect AI - Batch Inspection Report

Model Used: nano
Date: 2026-05-05 22:13:26.023126

Inspection Summary

Total Images: 4
Total Defects Detected: 4

Severity Distribution



corrosion_39_jpg.rf.d6bb0a82b7a6155d58bb65e799de5ee9.jpg



Severity: LOW

Defects: No issues detected


corrosion_90_jpg.rf.23f60c57cae9da98641ad1709ddfbdd1.jpg



Severity: LOW

Defects: No issues detected

rusted_car_2_jpg.rf.d292e8ec4b69a30c2546d0a061a5fd51.jpg



Severity: MEDIUM

Defects: Other defects detected

rusted_car_34_jpg.rf.24644a5727fc884b2e2840464b4c8b67.jpg



Severity: MEDIUM
Defects: Other defects detected

Generated by AeroInspect AI System