


AeroInspect AI - Batch Inspection Report

Model Used: custom
Date: 2026-05-09 12:09:53.397879

Inspection Summary

Total Images: 1
Total Defects Detected: 1

Severity Distribution



rusty_pipes_109_jpg.rf.7f9e56d646e797b6e76b8c1174797ea3.jpg



Severity: MEDIUM

Defects: Other defects detected

Generated by AeroInspect AI System