

Drone Inspection Report

Severity: HIGH

Detections:

Defects:

1 cracks detected

Alerts:

Structural crack detected

Inspection Image:

