

# Drone Inspection Report

**Severity: HIGH**

***Detections:***

boat - 0.45

***Defects:***

3 possible cracks detected

***Alerts:***

Crack detected — inspection required

***Inspection Image:***

